


FORD / UNI-FLANGE® INTRODUCES SERIES 1300-CAS MECHANICAL JOINT REPAIR KIT FOR DUCTILE IRON AND C900 PVC PIPE

Have you ever moved a fire hydrant, or water main spur, only to discover that an unrestrained joint exists because a thrust block has been disturbed? We all know the need to secure the joint is extremely important. Ford Meter Box provides an easy and cost-effective solution to this problem.


The new Uni-Flange® Series 1300-CAS Mechanical Joint Repair Kit addresses special needs encountered while installing new lines or repairing leaking joints that require restraint. The Uni-Flange® Mechanical Joint Repair Kit, UFR1300-CAS, is designed to repair leaks in existing mechanical joint installations. The two-piece gland and split gasket provide for easy installation on Ductile Iron or C900 PVC pipe. The UFR1300-CAS combines the ability to repair leaks with reliable thrust restraint on the existing joint.

The Ford Meter Box Company is committed to developing products that

solve the unique problems of our customers. For more information about the UFR1300-CAS, contact your local Ford distributor or call The Ford Meter Box Company, Inc.



Exploded view of the UFR1300-CAS



Assembled view of the UFR1300-CAS

